
Thank you for purchasing this quality product .Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.

Step 1:Please follow chart to assembly table leg B and table top A,But don't tinghten the long blot.



TOOLS REQUIRED(NOT PROVIDED): PHILLIPS SCREWDRIVER

PARTS LIST:					
NO.	Description	Sketch	Quantity		
A	Тор		1PC		
В	Leg		4PCS		

PARTS LIST:					
NO.	Description	Sketch	Quantity		
A	Тор		2PCS		
В	Leg		8PCS		

HAI	HARDWARE LIST:						
NO.	Description	Sketch	Size	Quantity			
С	Long Blot	(0)	Ø1/4"*2"L	24 PCS			
D	Lock Washer	0	ø 1/4"	24 PCS			
Е	Spring Washer	0	Ø 1/4"	24 PCS			
F	Allen Key		4mm	1PC			

NOTE: Straight Allen Key(k)is for use with a power drill.

